



Photo 1 – Airplane from front



Photo 2 – Airplane from left side



Photo 3 – Ground scarring



Photo 4 – Airplane from left rear



Photo 5 - Propeller



Photo 6 – Carburetor float bowl with fuel



Photo 7 – Spark plugs displaying carbon fouling