



Photo 1 – Accident Site



Photo 2 – Main Wreckage



Photo 3 – Left Propeller



Photo 4 – Left Propeller After Extraction



Photo 5 – Right Propeller



Photo 6 – Right Propeller After Extraction



Photo 7 – Right Wing



Photo 8 – Right Horizontal Stabilizer



Photo 9 – Left Wing



Photo 10 – Left Engine



Photo 11 – Throttle Quadrant



Photo 12 – Master Switches



Photo 13 – Left Engine’s Fuel and Ignition Switches




Photo 14 – Right Engine's Fuel and Ignition Switches



Photo 15 – Landing Gear Handle



Photo 16 – Autopilot Controls



Photo 17 – Underside of Right Wing



Photo 18 – Right Engine



Photo 19 – Right Engine's Oil Gage Housing Extension