



**Photo 1 – Photo taken at 0857 – View of the accident scene from the airplane’s left front**



**Photo 2 - Photo taken at 0859 – View of the accident scene from the airplane’s right side**



**Photo 3 - Photo taken at 0901 – View of airport perimeter road looking southwest**



**Photo 4 - Photo taken at 1006 – View from airplane’s left rear**



**Photo 5 - Photo taken at 1029 – View from airplane’s rear**



**Photo 6 - Photo taken at 1047 – View of ground scars, looking to the northeast**



**Photo 7 - Photo taken at 1035 – View of the west end of runway 10 R, looking to the east**