



**Photo 1 – View of substantial damage left wing aileron (Courtesy of FAA)**



**Photo 2 – View of substantial damage to the right landing gear trunnion (Courtesy of FAA)**



**Photo 3 – View of damage to right wing rib (Courtesy of FAA)**