



**Photo 1 – Overview of Accident Site**



**Photo 2 – Main Wreckage**



**Photo 3 – Tail Rotor/Empennage**



**Photo 4 – Wreckage Path**



**Photo 5 – Main Rotor Blades**



**Photo 6 –Tailboom Reconstruction**