



Photo 1 – Viewer is at the right front of the airplane which is enveloped in white smoke (Columbus Regional Airport Authority Photo)



Photo 2 – View from the airplane’s left side looking to the northeast (Columbus Regional Airport Authority Photo)



Photo 3 – View of damage to left engine cowling and tail cone (FAA Photo)



Photo 4 – View of damage to the rear of the left engine area (FAA Photo)



Photo 5 – View of damage to the top of the tail cone and left engine cowling (Cessna Photo)