



Photo 1 – View of Main Wreckage as Found



Photo 2 – View of Cut Tree Trunk Above Crash Site (Center Frame)



Photo 3 – View of Tree Trunk Section Displaying Angular Cuts and Slash Marks



Photo 4 – View of Angular Cut Tree Trunk with Fractured Propeller Tip Embedded



Photo 5 - View of Angular Cut Tree Trunk with Fractured Propeller Tip Embedded (Side View)