



**Photo 1 – Accident Site – FAA Photo**



**Photo 2 – Exhaust System – Lycoming Engine Photo**



**Photo 3 – Crack in Muffler – FAA Photo**



**Photo 4 – Muffler Shroud Lycoming – Lycoming Engine Photo**



**Photo 5 – Scat Tubing – FAA Photo**