



Photo 1 – Helicopter wreckage



Photo 2 – Helicopter wreckage



Photo 3 - Tail rotor




Photo 4 – Damaged main rotor blade



Photo 5 – Damaged main rotor blade



Photo 6 – Damaged main rotor blade



Photo 7 – Damaged main rotor blade



Photo 8 – Damaged main rotor blade



Photo 9 – Second damaged blade



Photo 10 – Third damaged blade