



Photo 1 – View of the accident site looking at the front of the airplane wreckage.



Photo 2 - View of the accident site looking at the left side of the airplane wreckage.



Photo 3 - View of the accident site looking at the aft side of the airplane wreckage.



Photo 4 - View of the accident site looking at the right side of the airplane wreckage.



Photo 5 - View of a ground scar by the nose of the airplane.



Photo 6 - View of the propeller in the ground scar.



Photo 7 - View of abrasion on a propeller blade.



Photo 8 - View of the canopy latch handle.



Photo 9 - View of a section of the canopy latch assembly.



Photo 10 - View of a section of the canopy latch assembly.



Photo 11 - View of the canopy roll bar.



Photo 12 - View of the carburetor and lower portion of the engine.



Photo 13 - View of the top of the engine.



Photo 14 - View of the wreckage from the end of the runway.



Photo 15 - View of removed sparkplugs.



Photo 16 - View of the data plate.



Photo 17 - View of the disassembled carburetor.



Photo 18 - View of the cockpit area.



Photo 19 - View of paint transfer in the ground scar.



Photo 20 - View of an elevator with its trim tab near a neutral position.