

Photo 1 – View looking at main wreckage from location of satchel.



Photo 2 – Main wreckage.



Photo 3 – Right wing and engine.



Photo 4 – Underside of left wing.



Photo 5 – Right wing after wreckage was up righted.



Photo 6 – Wreckage after it was up righted.



Photo 7 – Sections of propeller blade.



Photo 8 – Overall view of front of wreckage.



Photo 9 – Side view of left wing.



Photo 10 – Rear view of left wing.




Photo 11 – Top of engine and propeller hub.



Photo 12 – Cylinders 2 and 4




Photo 13 – Cylinders 1 and 3