



Photo 1 – View of the front of the airplane.



Photo 2 - View of the right side of the airplane.



Photo 3 - View of the rear side of the airplane.



Photo 4 - View of the left side of the airplane.



Photo 5 - View of the fuel line where pressurized air was applied.




Photo 6 - View of the engine and propeller.



Photo 7 - View of a magneto exhibiting spark at all leads.



Photo 8 - View of the boat ramp area where blight was present.



Photo 9 - View of a witness pointing to where the airplane impacted the lake.



Photo 10 - Wide angle view of the lake where the airplane impacted.