



**Photo 1 – Aerial view of the dog camp on the Denver Glacier**



**Photo 2 – Aerial view of the accident site**



**Photo 3 – Aerial view of the accident site**



**Photo 4 – View of fuselage**



**Photo 5 – View of fuselage and tailboom**



**Photo 6 – View of fuselage**



**Photo 7 – View of cockpit**



**Photo 8 – View of pilot's seat (right side)**





**Photo 9 – View of pilot’s seat (front side)**



**Photo 10 – View of pilot's seat (left side)**



Photo 11 – Bottom dog box



Photo 12 – Top dog box



**Photo 13 – Cargo straps**



**Photo 14 – Dog boxes prior to the accident (courtesy of the operator)**



**Photo 15 – Ground crew loading dogs into dog boxes prior to the accident (courtesy of the operator)**




Photo 16 – TEMSCO local operating area map