




**Photo 1 – Initial ground scar**



**Photo 2 – View of wreckage path with airplane in back ground**



**Photo 3 – View of damaged instrument panel**



**Photo 4 – View of fuselage and part of wing crushed.**



**Photo 5 – View of engine**



**Photo 6 – View of propeller**



**Photo 7 – View of damaged right wing**



**Photo 8 – View of damaged left wing**