



Photo 1 – Accident scene overview from 150 yards



Photo 2 – Initial impact and debris field



Photo 3 – Left wing impact point



Photo 4 – Right side of main wreckage



Photo 5 – Parachute canopy in the debris field



Photo 6 – C-APC T-handle with safety pin installed




Photo 7 – Entire flight track (Google Earth overlay)




Photo 8 – Flight track (Google Earth overlay)




Photo 9 – Flight track (Google Earth overlay)



Photo 10 – Final flight track facing north (Google Earth overlay)



Photo 11 - Final flight track facing south (Google Earth overlay)




Photo 12 – Radar track on IFR low enroute chart