



Photo 1 – Tire marks in grass (photo courtesy of FAA)



Photo 2 - Tire marks in grass (photo courtesy of FAA)



Photo 3 - Tire marks in grass (photo courtesy of FAA)



Photo 4 - Tire marks in grass and on taxiway (photo courtesy of FAA)



Photo 5 – Damaged fence post and accident airplane



Photo 6 – Airplane in ditch (photo courtesy of FAA)



Photo 7 – Airplane in ditch (photo courtesy of FAA)