



Photo 1 – Wreckage of N91038 in the silt laden waters of the Big Susitna River.




Photo 2 – Wreckage debris in the tidal mud flats on the east bank near the mouth of the Big Susitna River.



Photo 3 – Separated empennage from N91038.



Photo 4 – Gear box with main gear legs attached from N91038.



Photo 5 – Portion of fuselage from N91038.



Photo 6 – N9423B wreckage at Lake Hood Airport.



Photo 7 – N9423B wreckage at Lake Hood Airport.



Photo 8 – Cut right main tire from N9423B.




Photo 9 – Separated left main tire and gear leg from N9423B.



Photo 10 – Damage to belly of N9423B.