



Photo 1 – Impact point (circled in yellow) on rock face near ridgeline on south face of Goat Mountain.



Photo 2 – Discolored rock face at accident site.



Photo 3 – Accident airplane's propeller near ridgeline at accident site.



Photo 4 – Accident airplane's propeller at accident site.



Photo 5 –Thermally damaged accident airplane at accident site.



Photo 6 – Thermally damaged accident airplane at accident site looking south towards Girdwood, Alaska.