



**Photo 1 – Airplane in the grass near the runway**





**Photo 2 - Damaged and wrinkled left wing**





**Photo 3 – Damaged and curled propeller blades**