



Photo 1 – FAA supplied photo of the left rear quarter of the airplane. The airplane exhibits fuselage damage forward of its empennage.



Photo 2 - FAA supplied close up photo of the right rear quarter of the airplane. The airplane exhibits fuselage damage forward of its empennage.