



Photo 1 – Airplane at Accident Site



Photo 2 – Empennage



Photo 3 – Tailwheel Yoke



Photo 4 – Tailwheel Fork (Key Slide Fully Extended)



Photo 5 – Tailwheel Fork (Key Slide Stuck Fully Retracted)



Photo 6 – Tailwheel Fork (Disassembled)