



Photo 1 – Rear facing view of accident airplane at accident site.



Photo 2 – Left side view of accident airplane at accident site.



Photo 3 – Separated main fuel line of accident airplane.



Photo 4 – Accident airplane’s carburetor with staining evident.