



Photo 1 – View of damage to the left wingtip and landing gear (Courtesy of FAA)



Photo 2 – View of damage to the nose landing gear, left wing leading edge and the propeller (Courtesy of FAA)