



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety

Western Pacific Region

January 3, 2020

ACCIDENT REPORT PHOTOGRAPHS

WPR20CA060

This document contains 02 embedded photos.



Photo 1: Front View of Airplane (GSowards Onwer)



Photo 2: Damage to the wing outboard (GSowards Owner)