



Photo 1 – Accident airplane at accident site.



Photo 2 – Accident airplane at accident site.



Photo 3 – Airplane's engine buried in mud at accident site.



Photo 4 – Theodolite picture from rear of engine at accident site.



Photo 5 – Accident airplane's engine after removal from mud at accident site.



Photo 6 – Thermal damage to right fuel cap seal.



Photo 7 – Cracks around circumference of left fuel cap seal.