



Photo 1 – Airplane inverted and situated between trees



Photo 2 – Front and bottom of airplane inverted next to trees



Photo 3 – Fractured stabilator control horn




Photo 4 - Fractured stabilator control horn



Photo 5 - Fractured stabilator control horn