



Photo 1 – Image published in a local news source of the airplane resting in tree branches in the upper background and rescue workers in the lower foreground.



Photo 2 - FAA supplied view of the left side of the inverted airplane during recovery.



Photo 3 - FAA supplied view of the fuel tank selector. The selector is positioned to select both left and right tanks.



Photo 4 - FAA supplied view of the fuel tank gauges at the accident site. Both left and right fuel gauges have a full indication.



Photo 5 - FAA supplied view of the emergency locator transmitter at the accident site. The transmitter's switch is in the off position.