



Photo 1 – Airplane Wreckage (FAA Photo)



Photo 2 – Right Engine (FAA Photo)



Photo 3 – Aft Spar Abrasion Damage (FAA Photo)



Photo 4 – Left Auxiliary Tank Fuel Sample (FAA Photo)