



**NATIONAL TRANSPORTATION SAFETY BOARD**

Office of Aviation Safety  
Eastern Region

**Photo Array**

**ERA20CA140**



**Photo 1 –View of Inboard Section of Severed Wing (Photo Courtesy of Phoenix East Aviation)**



**Photo 2 – View of Severed Wingtip (Photo Courtesy of Phoenix East Aviation)**