



Fuel samples taken at the scene. From the left: right main tank, right aux, left aux, left main tank.



Fuel found in the fuel line headed to the engine. The fuel is discolored with an orange tint. This fuel was sent for analysis and the report is included in the public docket.