



Postcrash Changes at Crash Location

Tempe, AZ

HWY18MH010

(2 pages)



Photograph 1 – Shows that the paved areas in the median of North Mill Avenue were removed and covered with decomposed aggregate, larger stones and planted vegetation (*photograph copyright Arizona Republic 2019*)



Photograph 2 – This photograph of the median on North Mill Avenue, shows additional signs (back-to-back on originals) circled in red, were added to further dissuade pedestrian crossings (*photograph courtesy of the City of Tempe Arizona*)