

Figure 1 - Supplemental Power System Arrangement and Damage




Figure 2 - IMSAR Diagram of Step Up Transformer Wiring




Figure 3 - IMSAR Drawing of Step Up Transformer Wiring




Figure 4 - Manufacturer's Drawing of Step Up Transformer




Figure 5 - Interior View of Power Distribution Box (Looking forward)




Figure 6 - Step Up Transformer, Bus Block, and Grommeted Hole




Figure 7 - Step Up Transformer




Figure 8 - Step Up Transformer and Bus Block



Figure 9 - Step Up Transformer and Bus Block




Figure 10 - Grommeted Hole and Damaged Wires




Figure 11 - Grommeted Hole and Damaged Wires




Figure 12 - Diagram of Distribution Box Wiring Damage