



Powerplants 8 - Exhibit No. 8B - Photo 11. Left side of No. 1 engine thrust reverser in deployment position showing damage.