



Powerplants 8 - Exhibit No. 8B - Photo 12. Right side of No. 1 engine thrust reverser in deployed position showing damage.