



Powerplants 8 - Exhibit No. 8B - Photo 14. No. 1 engine thrust reverser lower door showing mud on interior surface.