

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: 2007	Total Time in Service TACH 415.3	Description PROP TT SMOH 2615.64 TTSDH 1100.80 REAPPLIED PROP GREASE AS NECESSARY
Date:		
Next Inspection Due:	Time Since Overhaul	400007
Mech. Cert. # or Repair Station #		

Year	Total Time		
Date	11--01-2014	Tach 616.2	Prop TT 2816.54 Prop SMOH 1307.7

Next Due: Completed an Annual Inspection In Accordance With Bellanca Service Manual. Researched AD's through Issue 2014-21. Cleaned, inspected, dressed and painted propeller. Greased Prop hub with Shell grease. I Certify This Propeller Has Been Inspected In Accordance With an Annual Inspection And Was Determined To Be In An Airworthy Condition.

Year

Date

Next Due: Charles Sojka I.A. [Redacted Signature]