

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL HC-C3YR-1RF

PROPELLER S/N DY6476B

LOGBOOK # 1

HARTZELL PROPELLER INC

INSPECTION

Part Number C3R00022

Date: 2/21/2005

Work Order # M060700

Model Number HC-C3YR-1RF/F7282									
Ass'y Ser No. DY6476B		Hydr Unit No. NA		Bulkhead No. NA		Valve No. NA		Dome No.	
Blade 1 K16453		Blade 2 K16457		Blade 3 K16455		Blade 4		Blade 5 Blade 6	
Carton No.	Lbs.	Weight	Kilos	Height	Width	Length	Packing		
Comments: Deice Kit: NA I.D.S# 793 10-25-04 Spinner Mounting Kit: NA 12.5 L.P./S.L. @ 30" Radius									
Packing Certified By: <i>RD</i>					Date: <i>2/22/05</i>				

PROPELLER MAINTENANCE RECORD

Position _____

PITCH RANGE

Propeller Model *HC-C3YR-1RF*

High/Feather *30.8/30.9*

PROPELLER MAINTENANCE RECORD

Position _____

Propeller Model HC-C34R-1RF

Propeller S/N DY6476B

Blade Design F7282

Blade S/N's

No. 1 K16453

No. 2 K16457

No. 3 K16455

No. 4 _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

PITCH RANGE

High/~~Feather~~ 30.8/30.9

Start Lock N/A

Low 12.5/12.6

Reverse N/A





Aircraft Manufacturer PIPER

Aircraft Model PA28R-200

S/N 28R-7635210

Registration N300KR

Date	T	Remarks	Signature	Signature
		<p>Date: 7/1/2005, Aircraft: N300KR, Type: PA28R-200, S/N: 28R-7635210, Hobbs: 182.7, Tach: 6322.9, Total Time: 6322.9, Engine - Type: IO-360-C1C, S/N: RL-14894-51A, Time: 2153.6, Prop Type: HC-C3YR-1RF, S/N: DY6476B, Time: 0.0 PTSO: New</p> <p>***Prop Work***</p> <p>Completed an Annual inspection in accordance with Piper inspection form and Service Manual. Removed Hartzell 2 bladed propeller m/n HC-C2YK-1BF, s/n CH5717 and installed new Hartzell, HC-C3YR-1RF/F7282, s/n DY6476B in accordance with STC#SA4529NM and installation procedures outlined in Hartzell Owner's Manual # 115N. See weight and balance and 337 this date. Ground run for ops and leak ck good.</p> <p>I certify that this propeller has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition.</p>	<input type="checkbox"/> Wisconsin Aviation - Madison 3606 Corben Court Madison, WI 53704 608-268-5003	<input checked="" type="checkbox"/> Wisconsin Aviation - Watertown 1741 River Drive Watertown, WI 53094 920-261-4567
		<p>Date: 10/25/2005, Aircraft: N300KR, Type: PA28R-200, S/N: 28R-7635210, Hobbs: 126.0, Tach: 6436.5, Total Time: 6436.5, Engine - Type: IO-360-C1C, S/N: RL-14894-51A, Time: 2267.2, Prop Type: HC-C3YR-1RF, S/N: DY6476B, Time: 113.6</p> <p>***Prop Work*** ID 1374</p> <p>Completed a 100 hr inspection in accordance with Piper PA28R-200 inspection form and Service Manual. Ground run for ops and leak ck good.</p> <p>I certify that this propeller has been inspected in accordance with a 100 hr inspection and was determined to be in airworthy condition.</p> <p>Benjamin J. Pitterle</p>	<input type="checkbox"/> Wisconsin Aviation - Madison 3606 Corben Court Madison, WI 53704 608-268-5003	<input checked="" type="checkbox"/> Wisconsin Aviation - Watertown 1741 River Drive Watertown, WI 53094 920-261-4567

Date	Date: 10/19/2007; Aircraft: N300KR; Type: PA28R-200; S/N: 28R-7635210; Tach: 6781.6; Total Time: 6781.6; Engine - Type: IO-360-C1C, S/N: RL-14894-51A, Time: 2612.3; Prop - Type: HC-C3YR-1RF, S/N: DY6476B, Time: 458.7 ***Prop Work*** ID 3251 Completed an Annual inspection. Ground run for ops and leak ck good. I certify that this propeller has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition. Benjamin J. Pitterle 				ves, ctions.
	<input type="checkbox"/> Wisconsin Aviation - Madison 3606 Corben Court Madison, WI 53704 608-268-5003				
					
	<input checked="" type="checkbox"/> Wisconsin Aviation - Watertown 1741 River Drive Watertown, WI 53094 920-261-4567				
	Date: 5/08/2008; Aircraft: N300KR; Type: PA28R-200; S/N: 28R-7635210; Tach: 6883.5; Total Time: 6883.5; Engine - Type: IO-360-C1C, S/N: RL-14894-51A, Time: 2714.2; Prop - Type: HC-C3YR-1RF, S/N: DY6476B, Time: 560.6 ***Prop Work*** ID 3890 Completed an Annual inspection, in accordance with FAR 43, Appendix D. Ground run for ops and leak ck good. I certify that this propeller has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition. Brian Wrage 				
	<input type="checkbox"/> Wisconsin Aviation - Madison 3606 Corben Court Madison, WI 53704 608-268-5003				
					
	<input checked="" type="checkbox"/> Wisconsin Aviation - Watertown 1741 River Drive Watertown, WI 53094 920-261-4567				

Date: 5/24/2011; Aircraft: N300KR; Type: PA28R-200; S/N: 28R-7635210; Tach: 7021.2; Total Time: 7021.2;
Engine - Type: IO-360-C1C, S/N: RL-14894-51A, Time: 2851.9; Prop - Type: HC-C3YR-1RF, S/N: DY6476B,
Time: 698.3

Prop Work

Completed an Annual inspection, in accordance with FAR 43, Appendix D. Ground run for ops and leak ck
good.

I certify that this propeller has been inspected in accordance with an Annual inspection and was determined
to be in airworthy condition.

Benjamin J. Pitterle

☐ Wisconsin Aviation - Madison
3606 Corben Court
Madison, WI 53704
608-268-5003



☐ Wisconsin Aviation - Watertown
1741 River Drive
Watertown, WI 53094
920-261-4567