

NATIONAL TRANSPORTATION SAFETY BOARD

RETENTION / RELEASE OF WRECKAGE RELATED TO ACCIDENT NUMBER ►

ACCIDENT NUMBER:

ERA19FA124

For Use In All Modal Investigations

REGISTERED OWNER (name and address) MARC, Inc [REDACTED] Brandon, MS 39042-2273		IDENTIFICATION NUMBER N400JM	
		MAKE Piper	
LOCATION Madeira, OH	DATE OF ACCIDENT 3/12/19	MODEL PA-31-350	
RETAINED BY NTSB REPRESENTATIVE Lynn Spencer		TITLE Air Safety Investigator	DATE 3/12/19
The National Transportation Safety Board has <input checked="" type="checkbox"/> has not <input type="checkbox"/> completed its investigation of the wreckage described above. All recovered wreckage except that listed in the evidence control form(s) is hereby released. <input checked="" type="checkbox"/> NO PARTS RETAINED			
RELEASED BY NTSB REPRESENTATIVE Lynn Spencer		TITLE Air Safety Investigator	DATE 1/15/2020
(This section may be acknowledged by a person, not the owner or owner's representative, who has knowledge of the disposition of the recovered wreckage and its parts. Such acknowledgement does not place responsibility for disposition of the wreckage upon that person.) I HEREBY ACKNOWLEDGE: <input checked="" type="checkbox"/> Receipt of the above described wreckage. <input type="checkbox"/> Removal of the parts, if any, listed in the evidence control form(s).			
PERSON MAKING ACKNOWLEDGEMENT ALLEN G. PL [REDACTED] ley		TITLE ADJUSTER	DATE 1-15-20
[REDACTED] CROWN		PHONE NUMBER & EMAIL [REDACTED]	
REMARKS: THE WRECKAGE IS IN STORAGE AT AME AVIATION, SPRINGFIELD, TN.			

NATIONAL TRANSPORTATION SAFETY BOARD EVIDENCE CONTROL	ACCIDENT NUMBER: ERA19FA124
--	---------------------------------------

For Use In All Modal Investigations

OFFICE Aviation Safety	DATE OF ACCIDENT 3/12/2019	ACCIDENT LOCATION (City & State) Madeira, OH
EVIDENCE OBTAINED BY:		
<input checked="" type="checkbox"/> EVIDENCE OBTAINED FROM:	LOCATION OR PERSON INFORMATION	DATE
<input type="checkbox"/> EVIDENCE RECEIVED FROM:	Madeira Police	3/13/2019
EVIDENCE CONTROL NUMBER ERA19FA124 - 02 - 02		GROUP
DESCRIPTION (<input type="checkbox"/> BIN ITEM - HAS BEEN SEPARATED <input type="checkbox"/> Garmin GPS		

OWNER OR OWNER'S REPRESENTATIVE

FIRST NAME: Allen G	LAST NAME: Plumley, ANPAC Adjuster
ADDRESS: [REDACTED] (aircraft in storage at AMF)	
PHONE: [REDACTED]	EMAIL: [REDACTED]
RETURNED <input checked="" type="checkbox"/>	DATE: 1/15/20
CONTACT: Lynn Spencer [REDACTED]	

CHAIN OF CUSTODY

RELEASED BY: Lynn Spencer	RELEASED TO: Recorder Lab	DATE: 3/19/19
PURPOSE: Acquire flight path and altitude data		
RELEASED BY: Recorder Lab	RELEASED TO: Lynn Spencer	DATE: 9/3/2019
PURPOSE: Hold until downloaded data can be analyzed		
RELEASED BY: Lynn Spencer	RELEASED TO: AMF	DATE: 1/15/2020
PURPOSE: Return to wreckage [REDACTED] 1/23/2020		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		

NATIONAL TRANSPORTATION SAFETY BOARD EVIDENCE CONTROL	ACCIDENT NUMBER: ERA19FA124
--	---------------------------------------

For Use In All Modal Investigations

OFFICE Aviation Safety	DATE OF ACCIDENT 3/12/2019	ACCIDENT LOCATION (City & State) Madeira, OH
EVIDENCE OBTAINED BY:		
<input checked="" type="checkbox"/> EVIDENCE OBTAINED FROM:	LOCATION OR PERSON INFORMATION	DATE
<input type="checkbox"/> EVIDENCE RECEIVED FROM:	AMF Aviation	4/29/19
EVIDENCE CONTROL NUMBER ERA19FA124 - 02 - 03		GROUP
DESCRIPTION (<input type="checkbox"/> BIN ITEM - HAS BEEN SEPARATED <input type="checkbox"/> Left nacelle fuel pump		

OWNER OR OWNER'S REPRESENTATIVE

FIRST NAME: AI	LAST NAME: Plumley
ADDRESS: AG Plumley, Inc. [REDACTED]	
PHONE: [REDACTED]	EMAIL: [REDACTED]
RETURNED <input checked="" type="checkbox"/>	DATE: 1/15/20
CONTACT: Lynn Spencer [REDACTED]	

CHAIN OF CUSTODY

RELEASED BY: AMF	RELEASED TO: Lynn Spencer	DATE: 4/29/19
PURPOSE: Further analysis		
RELEASED BY: Lynn Spencer	RELEASED TO: AMF [REDACTED]	DATE: 1/15/20
PURPOSE: Return to wreckage		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		