

Navajo Accessories, Inc.

F.A.A. Approved Rep. Sta. [REDACTED]

San Antonio, Texas 78216

Phone [REDACTED]

Work Order No.

81452 (NA157)

Customer P.O. No.

FAA verbal

Customer (Name)

FAA

Customer (Acct. #)

Date In

3-28-17

Out

3-29-17

Quantity

1

Mfg.

Slick

Aircraft No.

Serial No.

01120168

Waybill No.

TEARDOWN REPORT

PARTS USED

ACTION REQUESTED

X
ONR

QTY

PART NO.

NOUN

☐ Warranty ☐ Test Only ☐ Repair ☐ O.H. ☐ Core Evaluation ☐ Calibrated

EXTERNAL INSPECTION

☐ Assembled (normal configuration) ☐ Clean ☐ Dirty

☐ Disassembled (explain)

☐ Parts Missing (explain)

☐ Damaged or Failed (explain)

DISASSEMBLY

☒ Normal ☐ Difficulties (explain)

INTERNAL INSPECTION

☐ Clean ☒ Dirty (explain)

Rust, Corrosion

IMPLUSE RUSTED WANT WORK

☐ Parts Missing (explain) STUCK HAS FEAT STICK

ON ROTOR

☒ Parts Damaged or Failed (explain)

☐ All components
NORMAL wear

☐ All components
WITHIN tolerance

PROBABLE CAUSE OF FAILURE (opinion only)

☐ Normal wear - Time Change ☒ Other (explain)

Loose Stuck AND IMPLUSE DONT WORK

ACTION TAKEN

Warranty
Allowed

Warranty
Denied

Return
"As Is"

Scrapped
at Navajo

Core
Value \$

Assembled & Tested - Hose Assy.

Exchange

S/N
In:

S/N
Out:

MOD or SB
Compliance

By:

W.O. #

Repaired
and Tested

Insp. By:

Core Info:

Overhauled
and Tested

Functional
Test Only

Calibrated

LABOR

NR MATERIAL

ONR MATERIAL

EXC

CORE CHARGE

SHPG

DISCOUNT

CALIBRATION/TEST RESULTS

Evaluated 3 Inspected TAW

4300/6300 Slick/champion NA13000,
Revir, 12/09/2016.

Red TAGED

NAVAJO ACCESSORIES, INC.

F.A.A. Approved Rep. Sta. # [REDACTED]

San Antonio, Texas 78216

Rejected Part Tag

Work Order # 81952

Cust. Or. # FAR NA157

Owner FAR

Part Name LUCK MAGNET

Part # 4391

Serial # 01170148

Reason for Rejection RUST &

CORROSION

Inspected by [REDACTED]

Date 3/29/17

Navajo Accessories, Inc.

F.A.A. Approved Rep. Sta. # [REDACTED]
San Antonio, Texas 78216

Phone [REDACTED]

Work Order No. 51451 (NA150)

Customer P.O. No. FAA Verbal

Customer (Name) FAA

Customer (Acct. #)

Date In 3-28-17 Out 3-29-17

Item Slick magnet 4250 Quantity 1 Mfg. Slick

Part No. 4250 Aircraft No. Serial No. 7090045

Inv. No. Waybill No.

TEARDOWN REPORT

PARTS USED

I ACTION REQUESTED		X ONR	QTY	PART NO.	NOUN
☐ Warranty	☐ Test Only				
☐ Repair	☐ O.H.				
☐ Core Evaluation	☐ Cali-brated				
II EXTERNAL INSPECTION					
☐ Assembled (normal configuration)	☐ Clean				
☐ Dirty					
☐ Disassembled (explain)					
☐ Parts Missing (explain)					
☐ Damaged or Failed (explain)					
III DISASSEMBLY					
☒ Normal	☐ Difficulties (explain)				
IV INTERNAL INSPECTION					
☐ Clean	☒ Dirty (explain) Rust, Corrosion				
☐ Parts Missing (explain)					
☒ Parts Damaged or Failed (explain) Coil absolute, Capacitor Wipe pinched, Rust on shaft, Bearings rusted internally, Brush stuck, Rust.					
☐ All components NORMAL wear	☐ All components WITHIN tolerance				
V PROBABLE CAUSE OF FAILURE (opinion only)					
☐ Normal wear - Time Change	☒ Other (explain)				

CALIBRATION/TEST RESULTS

VI ACTION TAKEN		LABOR		DISCOUNT
Warranty Allowed	Warranty Denied			
Return "As Is"	Scrapped at Navajo	Core Value	\$	
Assembled & Tested - Hose Assy.				
Exchange	S/N In: [REDACTED]	S/N Out:		
MOD or SB Compliance	By: [REDACTED]	W.O. #		
Repaired and Tested	Insp. By: [REDACTED]	Core Info:		
Overhauled and Tested	[REDACTED]			
Functional Test Only				
Calibrated				

Evaluated 3 Inspected TAW
4300/6300 Slick/champion, NAI 3000,
Rev: IR, 12/09/2016.
Red Tagged

NAVAJO ACCESSORIES, INC.

F.A.A. Approved Rep. Sta. # [REDACTED]

San Antonio, Texas 78216

Rejected Part Tag

Work Order # 81951

Cust. Or. # FAA RAISE

Owner FAA

Part Name LUCK MAGNETO

Part # 4250

Serial # 4090045

Reason for Rejection EUST

+ CORROSION

[REDACTED]

Inspected by [REDACTED]

Date 3-29-17