



**Photo 1 – View to the southeast down runway 12. Note the skid mark angling off to the left (FAA photo)**



**Photo 2 – N9468W in the grass to the left of runway 12 (FAA photo)**



**Photo 3 – N9468W with collapsed nose landing gear (FAA photo)**



**Photo 4 – Left wing separation (FAA photo)**



**Photo 5 – Bent engine mount and buckled firewall (FAA photo)**



**Photo 6 – Wrinkle in roof next to cabin door handle (FAA photo)**



**Photo 7 – Torn skin on left wing and fuselage (FAA photo)**