



**Photo 1 – Tops of the trees.**



**Photo 2 - Right front of inverted N8559U at the accident site.**



**Photo 3 -Front of the airplane, exposing damage to the nose section and bottom of wings.**



**Photo 4 - Left front on inverted N8559U.**



**Photo 5 - Left side of airplane.**