



**Photo 1 – Right side of inverted Cessna R172K.**



**Photo 2 - N1095V at the crash site. Note burnt wing, grass, and tree trunk.**



**Photo 3 - Close-up view of severed right wing.**



**Photo 4 - Exposed instrument panel.**



**Photo 5 - The cabin area. Note airplane resting on power lines.**