



**Photo 1 – Pre-accident photograph of N670SR, a Cirrus SR22.**



**Photo 2 – The accident site in the rear of the Commemorative Air Force’s American Airpower Heritage Museum.**





**Photo 3 – Aerial view of the accident site.**





**Photo 4 – The ground scar, leading to the wreckage, measured 53 feet in length and was aligned on a magnetic course of 270°.**





**Photo 5 – Front view of the airplane.**





**Photo 6 – Propeller spinner and blade stub.**





**Photo 7 – Blade number 1.**





**Photo 8 – Blade number 2.**





**Photo 9 – Blade number 3.**





**Photo 10 – The instrument panel. The PFD screen is in the center and the MFD screen is to its right.**