



Photo 1 – Pre-accident photo of N14968.



Photo 2 – View to the southeast at the ground scar and debris path.



Photo 3 – View to the northeast from the debris field. 04Y's runway 16-34 is in far background.



Photo 4 – Bent main rotor blades and the ground scar left when it struck the ground. Note midspan bending.



Photo 5 – View to the north. Landing gear and tailboom frame are shown.



Photo 6 – View to the southeast. Rotor hub and rotor blade stubs are to the far left.