



SERVICE REQUEST FORM PLANTS

RSP111-14 Rev A

Date Printed: 05/05/10

Call Taken By:	WES MILLER	Date of Service Request:	04/29/10	Service Request #:	000431429
Service Initiator (Company):	ALLTRANSTEK LLC	Fax:	713		
Contact:	GENE FITZGIBBONS	Phone:	713		
Car #:	PPGX 001702	Car Type:	H.P. TANK		
Reason Shopped: HM 201					
DOT/AAR #:	105 J500W	BLT Date:	6-1979	17388	
Car Ower PAL:		Car Lessee PAL:		Fleet Manager PAL:	
Last Contents: CHLORINE			<input checked="" type="checkbox"/> Hazardous <input type="checkbox"/> Non-Hazardous		
<input type="checkbox"/> MSDS Required		<input type="checkbox"/> Cleaning Cert. Required		Car is : <input checked="" type="checkbox"/> Empty <input checked="" type="checkbox"/> Clean <input type="checkbox"/> Loaded	

Cleaning		
	BLAST	
	CLN - CHANGE OF SERVICE	
	INTERIOR WIPE	
	N2	
	OTHER	
Inspection		
	ASSIGNMENT	
	BAD ORDER	
	EWMA OPEN	
	FULL HM201	
	OTHER	
	PARTIAL HM201	
	PROGRAMS / MODIFICATIONS	
	REFLECTIVE TAPE	
	RULE 88B.2	
	SS3	
Valve		
	GASKET SPEC REQUIRED	
	N2	
	O-RING SPEC REQUIRED	
	OTHER	
	RUPTURE DISK MATERIAL	
	RUPTURE DISK PSI	
	VALVE TYPE	
	VLV MAINT / PM PROGRAM	
Interior Coating		
	COATING INSPECTION	



SERVICE REQUEST FORM PLANTS

RSP111-14 Rev A

Date Printed: 05/05/10

	COATING REPAIR	
	COATING REPLACEMENT	
	HATCH COVER / OUTLET GATE	
	OTHER	
Exterior Paint		
	CTR BAND REPAIR	
	CTR BAND REPLACEMENT	
	EXT PAINT REPAIR	
	EXT PAINT REPLACEMENT	
	OTHER	
	REFLECTIVE TAPE	

	Station	Qualified	Due
Tank Qualification	MRS	2000	2010
Thickness Test	MRS	2000	↓
Service Equipment	Redp	2006	
PRD Valve / vent PSI	Redp	2006	
Lining			
Type			
88-B-2	Redp	2006	↓
Stub Sill	Redp	2006	

**Apply Known CURRENT Station stencil info, tested dates and Due dates.
At arrival, all reported tested and due dates are to be confirmed.**