

Photo 1 – Wide view, microscopic image of fracture surface (Courtesy of Leonardo)




Photo 2 – Close view, microscopic image of crack propagation (Courtesy of Leonardo)