

DCA-13-MR-002
Derailment/Hazardous Materials Release
Paulsboro, NJ
November 30, 2012

ATTACHMENT 1

CA 11 Thorofare Detail

D 142

Site Name : Thorofare, NJ
Milepost : 11.0

Seq Number : 1406
DB Index # : 142

Direction : South
2012

Arrival : 07:36 11-30-

Speed In/Out: 19/23 MPH

Departure : 07:39

Slow Speed : 19 MPH

Amb Temp : Not Installed

Battery Voltage: 14.23

Axles : 340

Length : 4844.5 Feet

Alarms : 0

Cars : 84

Integ Fails : 0

Gate A Cnt : 340

System Warn : 0

Gate B Cnt : 340

Radio : On

DED Alarms : On

AUX Alarms : Off

Car Num	Axle Num	Spacing (Feet)	Alarms
---------	----------	----------------	--------

1	1	0.0	
	2	6.7	
	3	6.7	
	4	29.5	
	5	6.7	
	6	6.7	

2	7	12.3	
	8	6.7	
	9	6.7	
	10	29.4	
	11	6.7	
	12	6.6	

3	13	10.7	
	14	5.5	
	15	35.0	
	16	5.5	

4	17	12.0	
	18	5.7	
	19	40.0	
	20	5.7	

5	21	11.2	
	22	5.7	
	23	38.5	
	24	5.6	

6	25	10.9	
	26	5.6	
	27	53.0	
	28	5.6	

7	29	10.6
	30	5.6
	31	46.8
	32	5.6
8	33	7.1
	34	5.6
	35	49.9
	36	5.8
9	37	10.8
	38	5.8
	39	54.5
	40	5.8
10	41	10.8
	42	5.7
	43	39.7
	44	5.7
11	45	7.6
	46	5.7
	47	32.2
	48	5.7
12	49	7.7
	50	5.6
	51	30.7
	52	5.6
13	53	7.6
	54	5.6
	55	35.6
	56	5.6
14	57	7.6
	58	5.6
	59	35.3
	60	5.6
15	61	7.5
	62	5.6
	63	33.2
	64	5.8
16	65	7.9
	66	5.8
	67	31.7
	68	5.8
17	69	7.9
	70	5.8
	71	31.6

	72	5.8
18	73	7.8
	74	5.8
	75	35.8
	76	5.8
19	77	7.7
	78	5.8
	79	32.7
	80	5.7
20	81	7.8
	82	5.7
	83	31.1
	84	5.7
21	85	7.8
	86	5.7
	87	31.1
	88	5.7
22	89	7.8
	90	5.7
	91	35.3
	92	5.7
23	93	7.6
	94	5.7
	95	35.2
	96	5.7
24	97	7.6
	98	5.6
	99	35.1
	100	5.6
25	101	7.7
	102	5.6
	103	32.1
	104	5.6
26	105	7.5
	106	5.6
	107	44.7
	108	5.6
27	109	7.3
	110	5.6
	111	44.6
	112	5.6
28	113	7.4
	114	5.6

	115	28.6
	116	5.6
29	117	7.6
	118	5.6
	119	29.4
	120	5.6
30	121	7.6
	122	5.6
	123	28.4
	124	5.6
31	125	7.8
	126	5.6
	127	25.3
	128	5.6
32	129	7.9
	130	5.6
	131	38.4
	132	5.6
33	133	7.6
	134	5.6
	135	38.2
	136	5.6
34	137	7.9
	138	5.8
	139	38.0
	140	5.6
35	141	7.8
	142	5.8
	143	39.9
	144	5.8
36	145	7.9
	146	5.8
	147	39.8
	148	5.8
37	149	7.9
	150	5.8
	151	39.8
	152	5.8
38	153	7.9
	154	5.8
	155	37.8
	156	5.8
39	157	7.8

	158	5.8
	159	39.7
	160	5.8
40	161	7.9
	162	5.8
	163	38.0
	164	5.8
41	165	7.8
	166	5.8
	167	49.7
	168	5.8
42	169	7.8
	170	5.8
	171	40.0
	172	5.8
43	173	7.8
	174	5.8
	175	37.5
	176	5.8
44	177	7.7
	178	5.8
	179	40.4
	180	5.7
45	181	7.7
	182	5.8
	183	29.1
	184	5.7
46	185	7.6
	186	5.7
	187	46.3
	188	5.7
47	189	7.6
	190	5.7
	191	46.2
	192	5.7
48	193	9.9
	194	5.6
	195	39.8
	196	5.5
49	197	12.0
	198	5.5
	199	39.6
	200	5.5

50	201	9.7
	202	5.7
	203	40.5
	204	5.6
51	205	7.5
	206	5.6
	207	37.0
	208	5.6
52	209	7.6
	210	5.6
	211	39.8
	212	5.6
53	213	7.5
	214	5.6
	215	39.6
	216	5.7
54	217	7.5
	218	5.6
	219	35.2
	220	5.6
55	221	7.5
	222	5.6
	223	39.5
	224	5.6
56	225	7.5
	226	5.6
	227	39.3
	228	5.6
57	229	7.8
	230	5.6
	231	41.1
	232	5.8
58	233	7.7
	234	5.8
	235	41.0
	236	5.8
59	237	7.7
	238	5.8
	239	40.9
	240	5.8
60	241	7.6
	242	5.8
	243	40.7
	244	5.8

61	245	7.7
	246	5.8
	247	37.8
	248	5.8
62	249	7.9
	250	5.7
	251	37.4
	252	5.7
63	253	7.8
	254	5.7
	255	39.7
	256	5.7
64	257	7.6
	258	5.7
	259	40.5
	260	5.8
65	261	7.5
	262	5.8
	263	37.4
	264	5.7
66	265	7.5
	266	5.8
	267	39.9
	268	5.7
67	269	7.4
	270	5.7
	271	35.8
	272	5.7
68	273	8.1
	274	5.8
	275	36.2
	276	5.7
69	277	8.1
	278	5.7
	279	35.8
	280	5.7
70	281	7.4
	282	5.7
	283	37.4
	284	5.7
71	285	7.3
	286	5.7
	287	40.0

	288	5.7
72	289	7.4
	290	5.7
	291	39.8
	292	5.7
73	293	7.4
	294	5.7
	295	39.9
	296	5.6
74	297	7.4
	298	5.6
	299	39.7
	300	5.6
75	301	7.3
	302	5.6
	303	39.7
	304	5.6
76	305	7.4
	306	5.6
	307	39.6
	308	5.6
77	309	7.4
	310	5.6
	311	39.6
	312	5.6
78	313	7.4
	314	5.6
	315	38.8
	316	5.6
79	317	7.4
	318	5.6
	319	38.8
	320	5.6
80	321	7.4
	322	5.6
	323	38.8
	324	5.6
81	325	7.3
	326	5.6
	327	39.4
	328	5.6
82	329	7.3
	330	5.6

	331	38.9
	332	5.6
83	333	7.3
	334	5.6
	335	35.4
	336	5.6
84	337	7.4
	338	5.6
	339	35.2
	340	5.7

Some Parameters Have Been Defaulted...

All trains will report integrity failures until the "SETUP" command is executed

Thorofare, NJ, Single Track MP:11.0

Display >