HWY-15-MH-006 Metrolink Train Collision and Derailment with Service Truck and Trailer Oxnard, CA February 24, 2015

SIGNAL ATTACHMENT 14

Last_Six Months_C0406 South Oxnard_Monthly Tests 02272015



FRA Signal Inspection Reporting Test Locations with FRA Tests (Short-Will) Page Generated: 02/27/2015 12:16

▼Your selection criteria (Click the arrow to hide/unhide this section)

MSM: Younan, M I Subdivision: SANTA BARBARA SUB MP: 405.490 Segment: 6668-0nbsp; Track: SIMN Street: CO406 Asset Type: SWITCH Asset Desc: POWER OPERATED # 14 (R) From: 09/01/2014 To: 02/27/2015 Frequency: Monthly Include Unscheduled: Yes

▼Result Code legend (Click the arrow to hide/unhide this section)

Test Result Codes

C - Test complete. Equipment in satisfactory condition.
A - Adjustment made and test complete. Equipment in satisfactory condition.

R - Repairs or replacement needed.

S - Repairs or replacement made. Equipment in satisfactory condition.
 O - Out of service.

Other Codes u - Unscheduled Test

No.	Test Date	Date Found Requiring Test Repair Frequency	FRA FRA Test Rula Description	Equipment Yested or Inspected	Train Detection Device Name	Pre- Method determined Used Time	Actual Test Test Time Result Comment	Tested By
1	02/03/2015	Monthly	236.382 Switch Obstruction	POWER SWITCH			С	FLORES J R (engk922)
2	01/07/2015	Monthly	236.382 Switch Obstruction	POWER SWITCH			С	FLORES J R (engk922)
3	12/10/2014	Monthly	236.382 Switch Obstruction	POWER SWITCH			С	FLORES J R (engk922)
4	11/12/2014	Monthly	236.382 Switch Obstruction	POWER SWITCH			С	FLORES J R (engk922)
5	10/15/2014	Monthly	236.382 Switch Obstruction	POWER SWITCH			С	FLORES J R (engk922)
6	09/17/2014	Monthly	236.382 Switch Obstruction	POWER SWITCH			С	FLORES J R (engk922)
			Prin	t]	Back			