

# INSPECTION REPORT

Inspector's Name Sumoski, Charles J.		Inspector's Signature			Inspector's ID No 85938	Report No 36	Date yy mm dd 2016 04 04						
Railroad/Company Name & Address AMTRAK  Wilmington DE				R/C R  RR/Co Code ATK	Division SYSTEM  Subdivision PHIL-WASH MAIN	RR/Co Representative (Receipt Acknowledged) Name Robert Darren Slimbock Title Supervisor, C&S Email [REDACTED] Signature _____							
From: City CHESTER	Codes 1270	Destination City & County			Codes	From Latitude							
State PA	42	City				From Longitude							
County DELAWARE	C045	County				To Latitude							
Mile Post: From	To	Inspection Point				To Longitude							
Activity Code:	TCSO	TCSS	RWP										
Units:	2	1	1										
Sub Units:	0	0	4										
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ ***	Activity Code
1										N	N	0	
Description - [** Comment to Railroad/Company **] Attended an NTSB meeting to cover legal requirements of the investigation and to meet with other investigative partners, formed a discipline specific group and develop an investigation strategy. Met with Amtrak signal forces in the field, job briefed and began preliminary investigation of the signal system associated with the Amtrak Train No. 89 accident. Developed a plan for man power requirements to complete the signal testing the following day.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended				<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is:				<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?			