LOWER SKIN PANEL - WING CENTER TANK

CW-220 Z - 2673

GREEN

This is a small piece of stringer S-22 near the right S.O.B. that was separated from the skin panel. It showsall ductile failures and has some soot marks.

See attached sketch and photograph for specifics.

Wim Sten and 10/27/06 BOKING

SUGREEN 11/01/96 ALPA

Lougeles 11/4/96 FAA

North 11-26-26 TAM

Regulith 12-7-96 JAM

W. Sturpent 9/22/16

SPLICE FITTING
BOLT HOLE LOCAL SOOT DEPOSIT ON AFT SIDE AND TOP OF FREE FLANGE (ALSO SHOWS PEIMER DISCOLDIRATION) 33.

CENTER SECTION
LOWER STRINGER # 22
CW - 220
Z - 2673
CABEEN TAG